

VENCO - POTTERS WHEEL SPARE

SPARE PARTS:	AVAILABLE FOR:	Price including GST
	11" wheel Head + 3/4" shaft	No. 6 & No. 3-11" NO LONGER AVAILABLE
	13" wheel head + 1" shaft	No.3 - 13" & No.5 \$297.00
	Drive Wheel Assembly	All Cone Drive Wheels \$189.75
	<u>Bronze Bush 3/4" Shaft</u>	While stock lasts \$12.38 each
	<u>Bronze Bush 1" Shaft</u>	2 per wheel \$14.85 each
	Resilient Polyurethane shaft mounts (Grommets)	Cone Drive Models \$5.94 each No.3 & No.5 wheels have 8 off —4 large & 4 small
	'O' Rings	Cone Drive Models \$3.47 each
	Washer—Fibre	Cone Drive Models \$2.30
	Washer—Stainless Steel	Cone Drive Models \$2.30
	Spring—Small	Cone Drive Models \$9.90
	Spring—Large	Cone Drive Models \$22.10
	Shaft Locks (collars)	Cone Drive Models 28.05 each
	Motor—180w (1/4HP) + cradle & spring	Corresponding Wheels Approx. \$478.50 Price on application
	Motor—360w (1/2HP) + cradle & spring	Corresponding Wheels Approx. \$486.75 Price on application

Drive wheel Assembly

Resilient Polyurethane shaft mounts or Grom-

Small Spring
(Between motor and wheel head, hidden behind drive wheel Assembly)



There are two Bolts and nuts that hold the connection rod in place, if the grommet that they go through has been damaged you may need to replace one of these.



The bronze bush fits in the splash tray and the main shaft goes through it.

There are 2 on the wheel.

There are 2 'O' rings on the main shaft at the wheel head.

The washers make a set 2 Fibre and 1 steel.

There are 2 set on the wheel.

Service to your Venco Pottery Wheel.

All mechanical equipment need periodic servicing, to increase its life and to help you have trouble free performance when you need it.




Venco No3



Venco No5



Venco No6



Servicing your Venco Cone Driven Potters wheel.

(This covers the following Venco No. 6, No.3 and No.5)

Standard Service


- To check wheel and report on condition of Springs, Drive Wheel Assembly and the lead including the plug.
- To replace all Polyurethane shaft mounts (Grommets) (Remove all shafts, linkages and motor to do this.)
- To remove wheel head assemble and replace 'O' rings and fibre washers.
- To reassemble wheel, checking it and adjusting motor and wheel head.

Servicing Venco wheel \$375.40+ GST = \$412.95

Includes all parts and labour to do job as described. (Traveling time extra)

EXTRA

- to replace the drive wheel assembly is needed.



Red dot Small Grommets

Yellow dot Large Grommets

Replacing drive wheel assembly during a service.

\$210.00 + GST = \$231.00

Includes all parts and labour to do job as described. (Traveling time extra)